

2025 Access audit completed by HT & AHT January 2025

| Feature | Description | Actions to be taken | Person responsible | Date to complete actions by |
|--------------------|---|---|-----------------------------|-----------------------------|
| Corridor access | All corridors accessible for wheelchairs and wide enough to maneuver. During Co-vid 19 pandemic the corridors were further cleared of all non-essential storage to reduce chance of virus transmission making movement easier | Corridors to be kept tidy and free from obstructions | SLT & Site Supervisor | Ongoing |
| Parking bays | Parking bay available and clearly marked in the school car-park – first on right as you enter | Ensure staff do not park in the disabled bay unless a disabled badge holder | All school staff | Ongoing |
| Entrances | All entrances wide enough for wheelchair ingress and egress | Ensure equipment is not placed in front of or close to a door way, making the entrance narrower | All school staff and pupils | Ongoing |
| Ramps | Concrete ramps fitted for both of the rear main entrances to the building | Ramps installed by contractor | MH & FGB | 2021 |
| SEND Cabin | New Cabin installed Sept 2021 – door wide enough for Wheelchair access and ramp fitted at same time | Ramps installed by contractor | МН | 2021 |
| Toilets | Two disabled toilets in good condition | Ensure high standards of cleanliness and maintenance – additional mid-day cleaning now taking place | MH & site supervisor | Ongoing |

| Main school reception area | Access through locked gate and double doors – internal door operating on a mag lock | Be aware of visitors who may have disabilities and need assistance – there is a portable ramp to facilitate mortorised wheelchair access | Office staff | Ongoing |
|-------------------------------|--|--|----------------------------------|-------------|
| Internal signage | Main emergency signage in place & agreed by separate H&S and Fire Evacuation inspections Autumn 2022 | Ensure signs are not obscured by obstacles in the corridors | Site Supervisor & Headteacher | Autumn 2022 |
| Emergency escape routes | Emergency escape routes signed clearly and known by pupils | Ensure that emergency escape routes are not blocked by equipment, furniture or personal belongings | All school staff | Ongoing |